




F-16

Left side cover • Rectifier

Couvercle latéral gauche •
Rectificateur

Linker Seitendeckel •
Gleichrichter

Cubierta lateral izquierda •
Rectificador



B426-37

Service item	F.R.T.	Ref. No.	Part No.	Description	Reqd. No. CB650z	Serial No.	Area code
SPARK UNIT (ONE OR ALL)	0.2	1	30400-426-154	SPARK UNIT	2		
•STAY, REGULATE RECTIFIER		2	31403-300-000	RUBBER, REGULATOR CUSHION	2		
RECTIFIER ASSY., REGULATOR	0.3	3	31600-426-000	RECTIFIER ASSY., REGULATOR	1		
HOLDER, COUPLER	0.1	4	31601-426-000	STAY, REGULATE RECTIFIER	1		
•RELAY COMP., WINKER		5	32400-426-000	HOLDER, COUPLER	1		
•COVER COMP., L. SIDE		6	38301-404-611	RELAY COMP., WINKER (ND)	1		1, 2
		7	38301-404-612	RELAY COMP., WINKER	1		1, 2
			38301-415-004	RELAY COMP., WINKER	1		DK, DM, E, ED, F, U
		8	38306-292-000	SUSPENSION, WINKER RELAY	1		
		9	38306-405-612	SUSPENSION, WINKER RELAY (ND)	1		1, 2
		10	83551-300-000	BRACKET, AIR CLEANER CASE	3		